HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF/F7693DFB

PROPELLER S/N FP 3338B

LOGBOOK #_____

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model PHC-J3YF-1RF/F7693DFB

Propeller S/N FP3338B

Blade Design _____

Blade S/N's

No. 1 K12652

No. 2 K12649

No. 3 K12650

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus

Aircraft Model SR-22

S/N 1215

Registration N881WD

I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 10 dated Nov/03 Section: 61-00-15 on 11-23-01 (DATE).
The location of the Weight(s) are N/R degree
And are N/R gram(s).

MFG 79

C.J (Sign/Stamp)

Cirrus Design Corporation, PC 338CE

AAR AIRCRAFT SERVICES
OKLAHOMA

Disassembled, cleaned, reassembled with new seals and statically balanced propeller in accordance with Hartzell maintenance manuals 113B, 133C, 202A and 159. The propeller was repaired and inspected in accordance with current regulations of the Federal Aviation Agency. Pertinent details of the repair are on File under AAR work order 1001248.

PTSN: 149.6 **PTSO:** 149.6
Prop Model: PHC-J3YF-1RF **Serial Number:** FP338B **Blade Model:** F7693DFB
Blade SN: #1 – K12652 **#2** – K12649 **#3** – K12650

"APPROVED FOR RETURN TO SERVICE" DEC-09-2005

AAR
A-95

FOR AAR AIRCRAFT SERVICES-OKLAHOMA CRS JR2R936K

Will Rogers World Airport
6611 South Meridian
Oklahoma City, Oklahoma 73159

Rev. 6/25/02

Propeller Log PROP TT: 149.6

N#: 881WD S/N: 1215

Date: 12-12-2005 HM: 149.6 ACTT: 149.6

Midwest Corporate Aviation.

C/W Annual/ 100Hr inspection IAW Cirrus SR22 Maintenance Manual Inspection Guide and FAR 43appendix D.

- Performed 6 month propeller lubes per Hartzell MM.
- Cleaned and dressed blades.
- Ads checked thru this date, see compliance list.

I certify that this Propeller was repaired / inspected in accordance with an Annual/ 100HR inspection and was found to be in an airworthy condition. Pertinent details of the maintenance are on file at this repair station under W/O # 22680

_____ for Midwest Corporate Aviation, CRS# BVYR657C.

Midwest Corporate Aviation.

Propeller Log

PROP TT: 149.6

N#: 881WD
Date: 12-02-2005

S/N: 1215
HM: 149.6

Prop S/N: FP338B
ACTT: 149.6

Removed this Propeller, Model PHC-J3YF-1RF S/N FP338B, sent to AAR Aircraft Services Oklahoma, for repair of leaking grease seals, and reinstalled. Ops and leak checked, no defects noted.

I certify that this propeller was repaired / inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service for the work performed. Pertinent details of the maintenance are on file at this repair station under W/O # 22680

Paul D Hamel for Midwest Corporate Aviation, CRS# BVYR657C.

Midwest Corporate Aviation.

Prop S/N: FP3338B **_Propeller Log_** PROP TT: 204.8

N#: 881WD S/N: 1215

Date: 12-21-2006 HM: 204.8 ACTT: 204.8

- **C/W Annual inspection** IAW Cirrus SR22 Maintenance Manual Inspection Guide chap 5-10, 5-20 and FAR 43appendix D.
- Performed 6 month propeller lubes per Hartzell MM.
- Cleaned and dressed blades.
- Ads checked thru this date, see compliance list.

I certify that this Propeller was repaired / inspected in accordance with an Annual inspection and was found to be in an airworthy condition. Pertinent details of the maintenance are on file at this repair station under W/O # 28220.

_____ for Midwest Corporate Aviation, CRS# BVYR657C.



Prop S/N: FP3338B | ***Propeller Log*** | PROP TT: 224.6

N#: 881WD | | S/N: 1215

Date: 1-21-2008 | HM: 224.6 | ACTT: 224.6

Midwest Corporate Aviation.

- **C/W Annual inspection** IAW Cirrus SR22 Maintenance Manual Inspection Guide chap 5-10, 5-20 and FAR 43appendix D.
- Cleaned and dressed Propeller leading edges. Work done IAW Cirrus SR22 MM Chapter 61-10.
- Ads checked thru this date, see compliance list.

I certify that this Propeller was repaired / inspected in accordance with an Annual inspection and was found to be in an airworthy condition. Pertinent details of the maintenance are on file at this repair station under W/O # 23866

_____ for Midwest Corporate Aviation, CRS# BVYR657C.

WELLS AIRCRAFT, INC.
800 AIRPORT ROAD
MUNICIPAL AIRPORT
HUTCHINSON, KS 67501-1953
CRS NT2R043L
(620)663-1546
www.wellsac.com

Date: **01-22-2009**
Work Order: S6645
N881WD
Total Time: **250.1**
Hour Meter: **250.1**

PROP LOG

CIRRUS AIRCRAFT

Completed a 100 Hour Inspection with reference to Cirrus Maintenance Manual P/N 13773-001 Inspection Guide and Hartzell Propeller Manual P/N 115N. Dressed propeller blades as needed. **AD's complied with thru 07-26-09**. I certify that this Propeller (Hartzell PHC-J3YF-1RF S/N FP3338B) has been inspected in accordance with a **100 Hour Inspection** and was determined to be in an Airworthy Condition.

Authorized Signature Daniel Orpin

Daniel Orpin / CRS Release Authority

WELLS AIRCRAFT, INC.
800 AIRPORT ROAD
MUNICIPAL AIRPORT
HUTCHINSON, KS 67501-1953
CRS NT2R043L
(620)663-1546
www.wellsac.com

Date: **01-27-2010**
Work Order: S6878
N881WD S/N 1215

Flight Time: **414.8**
TTSN: **414.8**

PROP LOG

CIRRUS AIRCRAFT

Completed a 100 Hour Inspection with reference to Cirrus Maintenance Manual **P/N 13773-001 Rev A3** Inspection Guide and Hartzell Propeller Manual **P/N 115N. AD's complied with thru 2007-26-09**. I certify that this Propeller (**Hartzell PHC-J3YF-1RF, S/N FP3338B**) has been inspected in accordance with a **100 Hour Inspection** and was determined to be in an Airworthy Condition.

Authorized Signature: Daniel Orpin

Daniel Orpin / CRS Release Authority

WELLS AIRCRAFT, INC.
800 AIRPORT ROAD
MUNICIPAL AIRPORT
HUTCHINSON, KS 67501-1953
CRS NT2R043L
(620)663-1546
www.wellsac.com

Date: **02-04-2011**
Work Order: S7147
N881WD S/N 1215

Flight Time: **681.8**
TTSN: **681.8**

PROP LOG

Completed a 100 Hour Inspection with reference to Cirrus Maintenance Manual **P/N 13773-001 Rev A3** Inspection Guide and Hartzell Propeller Manual **P/N 115N**. **AD's complied with thru 2007-26-09**. I certify that this Propeller (**Hartzell PHC-J3YF-1RF, S/N FP3338B**) has been inspected in accordance with a **100 Hour Inspection** and was determined to be in an Airworthy Condition.

Authorized Signature: _____

Daniel Orpin / CRS Release Authority

PROP MODEL
PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: 881WD
WORK ORDER
14643-01-2012



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y
4514 Taylor Circle
Duluth, MN 55811
Phone: 218- 788-3438

DATE: 3/8/2012
A/C TSN: 986.6
PROP TT: 986.6
HOBBS: 986.6

Prop Entries

(5) Performed Propeller Annual/100 Hour Inspection IAW AMM ch. 5-20, researched airworthiness directives through bi-weekly issue 2012-04 all AD's are in compliance at this time.
(25) Dressed out nicks from leading edge of prop blades IAW Hartzell maint. practices and propeller owners manual 61-00-15 pages 6-17 through 6-20.
(26) Lubricated propeller hub with Aeroshell No.6 Grease IAW Hartzell Owners Manual section Maintenance Practices.
(128) I certify that this propeller has been inspected in accordance with an Annual/100HR inspection and was determined to be in airworthy condition.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS: YD5R855Y.

DATE: 3/8/2012

SIGNED:

Dave Ruuskanen
Certified Repair Station No. YD5R855Y

Work Order: 14643-01-2012

DATE 3-14-12 HOBBS/TACH 1024.2

DYNAMICALLY BALANCED LEFT/RIGHT (PROP) I/A/W

CHADWICK HELMUTH MANUAL "THE SMOOTH PROPELLER".

ADDED 18 GRAMS TO SPINNER

BULKHEAD/STARTER RING FOR A FINAL READING OF

.05 IPS

JOHN MATTSSONN IA 3330999

Airpower

HOBBS 1028.0
TOTAL 1028.0
TSOH -------
DATE 8/30/2012

AIRCRAFT MAINTENANCE & REPAIR
FALCON FIELD – MESA, AZ

REG # 881WD
A/C # 22-1215

PERFORM DYNAMIC PROPELLER BALANCE USING CHADWICK-HELMUTH SYSTEM. PERFORM SB2X-71-12R2 (INDUCTION PLENUM SUPPORT) . THIS AIRCRAFT IS APPROVED FOR RETURN TO SERVICE.

Bruce Taylor A/P: 3514310

LANDMARK AVIATION

14600 North Airport Drive • Scottsdale, AZ 85260 • (480) 948-2400

N881WD Date: April 4, 2013

Model: Cirrus SR22 SN: 1215

ACTT: 1073.9 HOBBS: 1073.9

PHC-J3YF SN: FP3338B PTT: 1073.9

PROPELLER LOG ENTRY

Accomplished 50 / 100 hour Annual inspection/lube in accordance with the Manufacturer's Service Manual.

Performed 100 hour / 12 month inspection and lubrication.

I certify that this **PROPELLER** has been inspected in accordance with a **100 HOUR** inspection and was found to be in an Airworthy Condition **W.O. C29-13-01166**

Landmark Aviation **FAA CRS# LN3R663L**

LANDMARK AVIATION

14600 North Airport Drive • Scottsdale, AZ 85260 • (480) 948-2400

N881WD Date: April 8, 2014

Model: Cirrus SR22 SN: 1215

ACTT: 1147.1 HOBBS: 1147.1

PHC-J3YF SN: FP3338B PTT: 1147.1

PROPELLER LOG ENTRY

Accomplished 50 / 100 hour Annual inspection/lube in accordance with the Manufacturer's Service Manual.

Performed 100 hour / 12 month inspection and lubrication.

I certify that this **PROPELLER** has been inspected in accordance with a **100 HOUR** inspection and was found to be in an Airworthy Condition **W.O. C29-14-01298**

Landmark Aviation **FAA CRS# LN3R663L**

PROP MODEL:
PROP S/N:
REG. NO: N881WD
WORK ORDER:
1268-04-2015

Lone Mountain Aircraft Maintenance

2460 Greentree Road
Hangar 12
Lebanon, Ohio 45036
Phone: 888-566-3686

DATE: 6/1/2015
A/C TSN:
PROP TT:
HOBBS: 1280.1

Prop Entries

(3) Propeller Annual Inspection... Complied with the Propeller annual inspection in accordance with the manufacturers maintenance manual. Serviced hub with Aeroshell #6 grease. Dressed blades as needed.... (6) Prop has nicks on all blades that require blending.... Blended Propeller as required.

This propeller has been inspected in accordance with a 100/annual inspection in accordance with the manufacturers maintenance manual and current FAA regulations and has been determined to be in an airworthy condition. END

DATE: 6/1/2015 SIGNED:

Ryan Yenger, IA 3669633

PROP MODEL:
PROP S/N:
REG. NO: N881WD
WORK ORDER:
1431-06-2016

Lone Mountain Aircraft Maintenance

2460 Greantree Road
Hangar 12
Lebanon, Ohio 45036
Phone: 888-566-3686

DATE: 7/8/2016
A/C TSN:
PROP TT:
HOBBS: 1444.9

Prop Entries

(3) Complied with the Propeller annual inspection in accordance with the manufacturers maintenance manual. Serviced hub with Aeroshell #6 grease. Dressed blades as needed.

This propeller has been inspected in accordance with a 100/annual inspection in accordance with the manufacturers maintenance manual and current FAA regulations and has been determined to be in an airworthy condition. END

DATE: 7/8/2016 SIGNED:

Ryan Yenger IA 3669633

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: N881WD
WORK ORDER:
1563-07-2017

Lone Mountain Aircraft Maintenance

2460 Greentree Road
Hangar 12
Lebanon, Ohio 45036
Phone: 888-566-3686

DATE: 7/19/2017
A/C TSN:
PROP TT:
HOBBS: 1516.5

Prop Entries

(3) Complied with the Propeller annual inspection in accordance with the manufacturers maintenance manual. Serviced hub with Aeroshell #6 grease. Dressed blades as needed.

This propeller has been inspected in accordance with a 100/annual inspection in accordance with the manufacturers maintenance manual and current FAA regulations and has been determined to be in an airworthy condition. ENO

DATE: 7/19/2017 SIGNED:

Ryan Yenger, IA: 3669633

Work Order: 1563-07-2017

PROP MODEL: PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: N881WD
WORK ORDER: 30569-10-2017

Commander Aero, Inc.

Repair Station No. GA5R-876M
10570 Springboro Pike
Miamisburg, Ohio 45342 USA
Phone: 888-881-5580

DATE: 10/30/2017
A/C TSN: 1542.6
PROP TT: 1542.6
HOBBS: 1542.6

Prop Entries

(4) Resealed prop deice boot edges and reglued delaminated sections of boot.

I certify that this propeller was inspected in accordance with a 100 hour inspection and found to be airworthy.
The aircraft and/or component(s) on N881WD was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 30569-10-2017.

DATE: 10/30/2017 SIGNED: Roger Romero

Romero, Roger
Certified Repair Station No. GA5R-876M

Work Order: 30569-10-2017

N881WD propeller TSN:1683.8 ACTT: 1683.8 8/20/18

Complied with 100 hour/Annual inspection items IAW SR22/SR22T Scheduled inspection report. Lubricated with AS#6. I certify that this propeller has been inspected IAW an Annual Inspection and is determined to be airworthy and approved for return to service.

Ricky E. Townsend A&P488843646IA

N881WD ~~engine~~ Prop # hourmeter: 1816.1 TSON:1816.1 TSTO:98.6 10/7/19

Complied with 100 hour/annual inspection items per SR22 scheduled inspection report. Lubricated with AS#6. Researched AD's and determined compliance to date. I certify that this propeller has been inspected IAW an Annual Inspection and is determined to be airworthy at this time.

Ricky E. Townsend a&P4888436461A

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: N881WD
WORK ORDER: 0789

Dedicated Aircraft Work
698 CR 1143
Tyler, TX 75704
Phone: 972-834-2476

DATE: 11/21/2020
A/C TSN: 1945
PROP TT: 1945
HOBBS: 1945

Prop
Overhaul

Prop Entries

Installed the propeller P/N PHC-J3YF-1RF S/N FP3338B after overhaul performed by Intercontinental Jet Services on work order PROP-2267 dated 10/15/2020.... Reinstalled the spinner dome P/N C-3532-5 S/N AI-3673 C after repair performed by K & K Precision Welding on work order 7626 dated 10/05/2020. Touched up paint as required.... Performed propeller 100HR/annual inspection in accordance with FAR 43 Appendix D using the Cirrus AMM 5-20 and 5-30 as a guide. Researched AD's through biweekly release 2020-23.

I certify this propeller has been inspected in accordance with a 100 hour/annual inspection and was determined to be in airworthy condition.

DATE: 11/21/2020 SIGNED: Work Order: 0789

Isaiah Daw, A&P: 2594100

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: 881WD
WORK ORDER: 4512

Chuck's Aircraft, LLC.

6200 Aviation Dr. AC101
Austin Executive Airport
Pflugerville, TX 78660
Phone: 512-610-3111

DATE: 11/24/2021
A/C TSN: 2047.4
PROP TT: 2047.4
TSPOH:
HOBBS: 2047.4

Prop Entries

Inspected blades, hub, spinner and backplate and TKS components.... Removed propeller and reinstalled with new o-ring p/n C-3317-228. Torqued propeller flange bolts IAW Hartzell Manual No. 145 Rev 18.

Technicians Who Worked On The Items Listed Above:
Colin Gangi, Reagan Penniman

This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.

DATE: 11/24/2021 SIGNED: Work Order: 4512

Colin Gangi, A&P: 4213181

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: N881WD
WORK ORDER: 0912

698 CR 1143
Tyler, TX 75704
Phone: 972-834-2476

DATE: 4/2/2023
A/C TSN: 2146.6
PROP TT: 2146.6
HOBBS: 2146.6

Prop Entries

Performed propeller 100HR/annual inspection in accordance with FAR 43 Appendix D using the Cirrus AMM 5-20 and 5-30 as a guide. Researched AD's through biweekly release 2023-06. Lubricated the propeller hub.... Dressed the propeller blades.... Adjusted the TKS feed tubes.

I certify this propeller has been inspected in accordance with a 100 hour/annual inspection and was determined to be in airworthy condition.

DATE: 4/2/2023 SIGNED: Work Order: 0912

Isaiah Daw, A&P: 2594100

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: N881WD
WORK ORDER:
6678-04-2024

Houston Aviation Center, LLC

12888 Hwy 6 S Ste 113
Sugar Land, TX 77498 USA
Phone: 281-494-5800

DATE: 6/17/2024
A/C TSN: 2217.1
PROP TT: 2217.1
TSPOH: 172.1
HOBBS: 2217.1

Prop Entries

Completed a 100 HR/Annual Inspection this date Ref CDC SR22 AMM 5-20 and Hartzell Propeller Owner's Manual No. 115N. Inspected and dressed propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked ADs thru BW 2024-12.... I certify that this Propeller has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.

Maintenance Release

The aircraft and/or component(s) on N881WD was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 6678-04-2024.

DATE: 6/17/2024 SIGNED: Work Order: 6678-04-2024

Fouad Hussain, A&P: 3204861 IA

MAKE: Cirrus
MODEL: SR22
S/N: 1215
REG. NO: N881WD
PROP MN: PHC-J3YF-1RF

Dedicated Aircraft Work
698 CR 1143
Tyler, TX 75704


W/O #: 1115
DATE: 06-17-2025
Hobbs: 2269.5
A/C TT: 2269.5
Prop TT: 2269.5

Entries

Performed propeller 100HR/annual inspection in accordance with FAR 43 Appendix D using the Cirrus AMM 5-20 and 5-30 as a guide. Researched AD's through biweekly release 2025-11. Lubricated the propeller hub.

I certify this propeller has been inspected in accordance with a 100 hour/annual inspection and was determined to be in airworthy condition.

DATE: 06-17-2025

SIGNED: 

Isaiah Daw
A&P or IA Number: 2594100

WORK ORDER: 1115

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3338B
REG. NO: N881WD
WORK ORDER:
7049-05-2026

Houston Aviation Center, LLC
12888 Hwy 6 S Ste 113
Sugar Land, TX 77498 USA
Phone: 281-494-5800

DATE: 7/16/2026
A/C TSN: 2295.1
PROP TT: 2295.1
TSPOH: 250.1
HOBBS: 2295.1

Prop Entries

Completed a 100 HR/Annual Inspection this date Ref CDC SR22 AMM 5-20 and Hartzell Propeller Owner's Manual No. 115N. Inspected and dressed propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked ADs thru BW 2026-14.... I certify that this Propeller has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.

Maintenance Release

The aircraft and/or component(s) on N881WD was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 7049-05-2026.

DATE: 7/16/2026 SIGNED:

Fouad Hussain, A&P: 3204861 IA

Work Order: 7049-05-2026